

Systems of floors maintenance

No	Routine	Special	Periodic	Application
1	Sweep			Loose soiling. Light to heavy traffic
2	Sweep. Damp mop or wet mop using single-solution method	Wet mop using two-solution method with neutral detergent		Light to moderate soiling. Light to heavy traffic. Floor requires no additional protection
3	a) Sweep. Spray clean with neutral detergent, buffable detergent or gel cleaner. b) Sweep. Damp or wet mop using single – solution method with buffable detergent or gel. Buff. (Sweep)	Wet mop using two-solution method with neutral detergent	Light scrub with neutral detergent to remove film of resin, detergent, oil, fats and soil	Light to moderate soiling. Light to heavy traffic. Floor requires no additional protection. Gloss required
4	a) Sweep. Spray clean with buffable detergent or gel. (Sweep)	Wet mop with neutral detergent using two-solution method or light scrub Scrub and apply polish to worn areas	Spray strip or scrub with alkaline detergent. Apply 1 to 3 coats of dri-bright polish depending on amount of wear expected. Use a metallized polish if scrubbing of the floor is to occur with any regularity and strip with an ammonia stripper	Light to moderate soiling. Light to heavy traffic. Protection of floor required. Gloss required
5	a) Sweep. Spray burnish with buffable detergent or gel. (Sweep) b) Sweep. Damp or wet mop using single-solution method with neutral detergent, buffable detergent or gel cleaner. Buff (Sweep)	Wet mop using two-solution method with a neutral detergent. Burnish. Light scrub and apply coat of polish to worn areas	Scrub with solvent based detergent. Apply 2 to 3 coats of solvent based polish	Wood floors; no seal used
6	a) Sweep. Spray burnish with liquid solvent based polish. (Sweep) b) Sweep. Damp mop or wet mop using single-solution method with neutral detergent. Buff. (Sweep)	Wet mop using two-solution method with neutral detergent. Burnish. Light scrub and apply coat of polish to worn areas	Scrub with solvent-based detergent. Apply 2 to 3 coats of solvent based polish	Wood floors; no seal used

7	Sweep. Wet mop using two-solution method or light scrub with neutral detergent	Scrub with neutral detergent		Heavy soiling. Light to heavy traffic. Floor requires no additional protection. No gloss required. Not floors affected by excessive wetting
8	Sweep. Wet mop using two-solution method or light scrub with neutral detergent. Buff if required	Light scrub with neutral detergent and apply a coat of polish to worn areas	Spray strip or scrub with (ammonia) stripper. Apply 2 to 3 coats of metallized polish	Heavy soiling. Moderate to heavy traffic. Floor requires protection. Gloss required. Frequent scrubbing necessary
9	Sweep. Light scrub using scrubber drier. Buff if required. (Sweep)	Apply coat of polish to worn areas if polish used	Apply up to three coats of metallized polish if floor requires protection or a gloss is required	Large areas of floor. Light to heavy soiling. Not floors affected by regular wetting